



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

May 21, 2008

Reviewed: *TR*

Mine Name: Rosebud	Permit Number: M/003/0026
Operator Name: Star Stone Quarries, Inc.	Inspection Date: March 19, 2008
Inspector(s): Lynn Kunzler	Time: 8:30 am
Other Participants: None	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Routine Inspection while in the area

Inspection Summary:

This site is considered active, even though there was no activity during this inspection. Activity has been occurring at both pits, with several hundred pallets of stone ready for shipping. Most garbage has been cleaned up. The trackhoe on site had a broken hydraulic line and had spilled a significant amount of oil on the ground. This will need to be cleaned up. Fuel storage has secondary containment with no fuel or oil barrels outside the secondary containment area.

The reclamation surety for this site is overdue for escalation.

Photos were taken to document site conditions.

Conclusions and Recommendations:

DOGM's bonding coordinator needs to contact this operator to initiate the surety escalation.

Continue to monitor this site when in the area.

Inspector's Signature *LK*

LK:pb

cc: Lon Thomas, Operator

Larry Garahana, BLM-SLC FO

Jed Pearson, DOGM Bond Coordinator

O:\M003-BoxElder\M0030026-Rosebud\inspections\Insp-03192008.doc